

Read Me

ATTO FIRMWARE

Epci0168.exe is a self-extracting file which contains version 1.68 ATTO SCSI driver and firmware installers. For Windows XP systems, use the driver and installers located in the NT folder. It is very important that you carefully read and follow the installation instructions, which are packaged along with the v1.68 driver update and firmware files.

